

FCA




FLEXIBLE CONNECTOR ADHESIVE

THE SENSIBLE SOLUTION TO MAKING YOUR FLEXIBLE DUCT CONNECTOR SEAM!

Follow these simple steps to join your flexible duct connector together.

1. Cut away 1-1/2" of metal from one side of your connector, leaving a 1-1/2" tongue of fabric. (Fig. 1)
2. Overlap connector ends 1-1/2" and screw or weld together. (Fig. 2)
3. Apply one or two lines of FCA, sparingly, on fabric, under tongue. (Fig. 3)
4. Press tongue down on adhesive. Rub gently and hold for 10 seconds. (Fig. 3)
5. For an airtight connection, apply duct sealer over metal joint.



Available in 1 oz. bottles from your local Duro Dyne Distributor.

Store in a cool, dry place.

Shelf Life: 3-6 months

Not recommended for Teflon.

Ordering Information

Item #	Code	Description	Qty
5090	FCA	Flexmastic Adhesive - 1oz Bottle	6 per box

Duro Dyne Corporate Headquarters, Bay Shore, NY
631-249-9000 • Fax: 631-249-8346
Duro Dyne Midwest • Duro Dyne West • Duro Dyne Canada
www.durodyne.com • E-mail: durodyne@durodyne.com



© Duro Dyne Corp.
Printed in USA 8/3/2020
FCA0599